

ABSTRACT OF THE DISCLOSURE

When a trunk lid 10 is opened, even in the case that the trunk lid 10 is attached to a weather strip due to a frost of a vehicle body and the trunk lid 10 is not sufficiently opened, a lock canceling member 60 is restricted at an restriction canceling position
5 during a period that a striker 45 is returned to a waiting position from a bring-in position. Furthermore, a latch 31 is not again engaged with the striker 45, and a drive mechanism 50 does not bring in the trunk lid 10 again.